

---

# MicroEJ SDK Errata



**MICROEJ**®

Reference  
Revision

TLT-0785-MAN-Errata  
2.1

### ***Confidentiality & Intellectual Property***

All rights reserved. Information, technical data and tutorials contained in this document are confidential and proprietary under copyright Law of Industrial Smart Software Technology (IS2T S.A.) operating under the brand name MicroEJ®. Without written permission from IS2T S.A., *copying or sending parts of the document or the entire document by any means to third parties is not permitted*. Granted authorizations for using parts of the document or the entire document do not mean IS2T S.A. gives public full access rights.

The information contained herein is not warranted to be error-free. IS2T® and MicroEJ® and all relative logos are trademarks or registered trademarks of IS2T S.A. in France and other Countries.

Java™ is Sun Microsystems' trademark for a technology for developing application software and deploying it in cross-platform, networked environments. When it is used in this documentation without adding the ™ symbol, it includes implementations of the technology by companies other than Sun.

Java™, all Java-based marks and all related logos are trademarks or registered trademarks of Sun Microsystems Inc, in the United States and other Countries.

Other trademarks are proprietary of their authors.

## Table of Contents

1. MicroEJ SDK 4.1.0 .....	4
1.1. Tools Limitations .....	4
2. MicroEJ SDK 4.0.0 .....	5
2.1. Core Engine Limitations .....	5
2.2. MicroUI Limitations .....	5
2.3. Network Limitations .....	7
2.4. Tools Limitations .....	8
3. MicroEJ SDK 3.1.2 .....	9
3.1. Low Level API Implementation Limitations .....	9
3.2. Tools Limitations .....	9
4. MicroEJ SDK 3.1.1 .....	11
4.1. Low Level API Implementation Limitations .....	11
4.2. Tools Limitations .....	11
5. MicroEJ SDK 3.1.0 .....	13
5.1. Low Level API Implementation Limitations .....	13
5.2. MicroUI Limitations .....	13
5.3. Tools Limitations .....	14
6. MicroEJ SDK 3.0.0 .....	16
6.1. Core Engine Limitations .....	16
6.2. MicroUI Limitations .....	16
6.3. Tools Limitations .....	16
7. Document History .....	17

## 1 MicroEJ SDK 4.1.0

### 1.1 Tools Limitations

#### 1.1.1 Addon processor builder is not triggered when reactivating Automatic Build

Issue #19491

##### Description

If Project > Build Automatically is enabled after creating a project which may use and Addon processor, this Addon processor is not triggered.

##### Workaround

Clean manually the project: click on the project and go to Project > Clean..., choose Clean projects selected below and press OK.

#### 1.1.2 Virtual device build error when platform location contains accents

Issue #16126

##### Description

This is an issue related to projects generated by an EasyAnt skeleton. If the path where the project is generated or the name of the project itself contains accents, the module.ivy, .classpath, and .project files contains invalid characters, and would not be understood by the IDE.

##### Workaround

Avoid generating an EasyAnt project into a path containing accents.

## 2 MicroEJ SDK 4.0.0

### 2.1 Core Engine Limitations

#### 2.1.1 MicroEJ Launch silently ignored when license unavailable

Issue #16262

##### Description

When executing a MicroEJ launch with no license, nothing happens. The same happens when there are errors in the MicroEJ launch configuration.

##### Workaround

Plug a dongle or add a valid Evaluation license.

#### 2.1.2 ByteArray.set() and ByteArray.clear() don't modify the first byte

Issue #16434

##### Description

The methods `ByteArray.set()` and `ByteArray.clear()` skip the first byte and they don't check correctly the bounds.

##### Workaround

Set the offset parameter at `offset - 1` and the length parameter at `length + 1`.

#### 2.1.3 Error when inlining a method that calls an abstract method

Issue #16502

##### Description

The SOAR may generate invalidate code when inlining a method that calls an abstract method with one implementation. This occurs when the implementation of the abstract method has try/catch blocks.

##### Workaround

none.

#### 2.1.4 Debug/Variables view doesn't display correct values for static final double

Issue #17032

##### Description

When adding a static final double variable in the Debug/Variables the value is not displayed correctly.

##### Workaround

Display the value with a `System.out.println()`.

### 2.2 MicroUI Limitations

#### 2.2.1 Image width in format A1 is sometimes invalid

Issue #16233

### **Description**

A wrong width is stored in RAW image. Rendering is correct but the value returned by `Image.getWidth()` may be invalid.

### **Workaround**

Use RAW format A2 instead.

### **2.2.2 Transformation of A1, A2 and A4 images is wrong**

Issue #16278

### **Description**

Deform, rotate and scale renderings are wrong. Read a pixel from this kind of image returns an invalid value.

Note: transformation "flip" is working.

### **Workaround**

use A8 images instead.

### **2.2.3 A built-in bold font is not tagged as bold font**

Issue #16455

### **Description**

A built-in bold font is not recognized as a bold font but as a plain font. So retrieve this kind of font using style `Font.STYLE_BOLD` does not work.

### **Workaround**

Use a specific font identifier to retrieve the font.

### **2.2.4 Wrong rendering when rotating images in format A1, A2 or A4**

Issue #16579

### **Description**

When rotating an image stored in RAW format A1, A2 or A4, the rendering is invalid.

### **Workaround**

Use RAW format A8 instead.

### **2.2.5 Wrong rendering when drawing a part of image in format A1, A2 or A4**

Issue #16632

### **Description**

When drawing a part of an image stored in RAW format A1, A2 or A4, the rendering may be invalid.

### **Workaround**

Use RAW format A8 instead.

### **2.2.6 Runtime exception when converting an image on the MicroEJ Simulator**

Issue #16701

**Description**

A call to `Image.convert()` throws a runtime exception.

**Workaround**

none.

**2.2.7 Some drawings may not performed when using a `GraphicsContext` created by a call to `Display.getNewGraphicsContext`**

Issue #17400

**Description**

This kind of `GraphicsContext` forces a LCD refresh after each drawing action. When the last drawing is hardware accelerated and asynchronous, the LCD refresh is not waiting the end of drawing. The rendering is so invalid.

**Workaround**

Use a `GraphicsContext` created by a call to `Display.getNewExplicitFlush` and manage yourself the LCD refresh.

**2.2.8 A RAW image in A1, A2 or A4 format is rendered with "too bright" pixels.**

Issue #17901

**Description**

The original is first converted in a grayscale image. This first conversion outs pixels "too bright".

**Workaround**

Use A8 images instead.

**2.3 Network Limitations****2.3.1 IPv4 addresses containing a ".0." string are considered invalid**

Issue #17125

**Description**

When setting the IP address, the values containing a ".0." string are considered invalid, which makes it impossible to setup a static IPv4 address in the 192.168.0.0 subnet (for example).

**Workaround**

none.

**2.3.2 Unknown hosts on multiple CNAME entries**

Issue #17923

**Description**

When resolving multiple CNAME entries (meaning a chain of aliases), an unknown host exception is incorrectly thrown.

**Workaround**

none.

### **2.3.3 Receiving UDP datagrams are limited on reception**

Issue #17949

#### **Description**

If the size exceeds an internal limit (256 bytes), the whole packet is not read without warnings or errors and 256 is returned as the processed reading length.

#### **Workaround**

When allocating a datagram packet specifying an Immortal byte array of the wanted size solves the issue.

## ***2.4 Tools Limitations***

### **2.4.1 Plugin installation issue with platform import.**

Issue #11022

#### **Description**

After installing a XPFP UI with a newer version of the frontpanel than the SDK, the workbench seems "to see" the plugin (cf configuration details) but it doesn't install it.

#### **Workaround**

Install the plugin manually.



## 3 MicroEJ SDK 3.1.2

### 3.1 Low Level API Implementation Limitations

#### 3.1.1 Core engine scheduling stopped on uCOS-II or uCOS-III

Issue #12202

##### Description

The core engine may stop to schedule MicroEJ application threads when a task with a higher priority than the core engine task prevents the execution of the core engine.

##### Workaround

The LLMJVM implementation must be updated:

*LLMJVM over uCOS-II*

```
static INT32U LLMJVM_UCOSII_timeToTick(int64_t time)
{
  if(time < 0)
  {
    return 0;
  }
  int64_t ticks64 = ((time * (int64_t)OS_TMR_CFG_TICKS_PER_SEC) + 999LL) / 1000LL;
  INT32U ticks = (INT32U) ticks64;

  // Saturate the value to the max value for a INT32U.
  if(ticks != ticks64)
  {
    ticks = DEF_INT_32U_MAX_VAL;
  }
  return ticks;
}
```

*LLMJVM over uCOS-III*

```
static OS_TICK LLMJVM_UCOSIII_timeToTick(int64_t time)
{
  if(time < 0)
  {
    return 0;
  }
  int64_t ticks64 = ((time * (int64_t)OSCfg_TmrTaskRate_Hz) + 999LL) / 1000LL;
  OS_TICK ticks = (OS_TICK) ticks64;

  // Saturate the value to the max value for an OS_TICK.
  if(ticks != ticks64)
  {
    return DEF_INT_32U_MAX_VAL;
  }
  return ticks;
}
```

### 3.2 Tools Limitations

#### 3.2.1 Heap Dumper does not strip XML comments related to string literals

Issue #15348

##### Description

Heap Dumper is not able to load heap files which contains some Unicode characters whereas these characters are allowed in XML comments.

**Workaround**

Remove all Unicode characters in XML comments.

**3.2.2 Plugin installation issue with platform import.**

Issue #11022

**Description**

After installing a XPFP UI with a newer version of the frontpanel than the SDK, the workbench seems "to see" the plugin (cf configuration details) but it doesn't install it.

**Workaround**

Install the plugin manually.

## 4 MicroEJ SDK 3.1.1

### 4.1 Low Level API Implementation Limitations

#### 4.1.1 Core engine scheduling stopped on uCOS-II or uCOS-III

Issue #12202

##### Description

The core engine may stop to schedule MicroEJ application threads when a task with a higher priority than the core engine task prevents the execution of the core engine.

##### Workaround

The LLMJVM implementation must be updated:

*LLMJVM over uCOS-II*

```
static INT32U LLMJVM_UCOSII_timeToTick(int64_t time)
{
  if(time < 0)
  {
    return 0;
  }
  int64_t ticks64 = ((time * (int64_t)OS_TMR_CFG_TICKS_PER_SEC) + 999LL) / 1000LL;
  INT32U ticks = (INT32U) ticks64;

  // Saturate the value to the max value for a INT32U.
  if(ticks != ticks64)
  {
    ticks = DEF_INT_32U_MAX_VAL;
  }
  return ticks;
}
```

*LLMJVM over uCOS-III*

```
static OS_TICK LLMJVM_UCOSIII_timeToTick(int64_t time)
{
  if(time < 0)
  {
    return 0;
  }
  int64_t ticks64 = ((time * (int64_t)OSCfg_TmrTaskRate_Hz) + 999LL) / 1000LL;
  OS_TICK ticks = (OS_TICK) ticks64;

  // Saturate the value to the max value for an OS_TICK.
  if(ticks != ticks64)
  {
    return DEF_INT_32U_MAX_VAL;
  }
  return ticks;
}
```

### 4.2 Tools Limitations

#### 4.2.1 Heap Dumper does not strip XML comments related to string literals

Issue #15348

##### Description

Heap Dumper is not able to load heap files which contains some Unicode characters whereas these characters are allowed in XML comments.

**Workaround**

Remove all Unicode characters in XML comments.

**4.2.2 Plugin installation issue with platform import.**

Issue #11022

**Description**

After installing a XPFP UI with a newer version of the frontpanel than the SDK, the workbench seems "to see" the plugin (cf configuration details) but it doesn't install it.

**Workaround**

Install the plugin manually.

## 5 MicroEJ SDK 3.1.0

### 5.1 Low Level API Implementation Limitations

#### 5.1.1 Core engine scheduling stopped on uCOS-II or uCOS-III

Issue #12202

##### Description

The core engine may stop to schedule MicroEJ application threads when a task with a higher priority than the core engine task prevents the execution of the core engine.

##### Workaround

The LLMJVM implementation must be updated:

*LLMJVM over uCOS-II*

```
static INT32U LLMJVM_UCOSII_timeToTick(int64_t time)
{
  if(time < 0)
  {
    return 0;
  }
  int64_t ticks64 = ((time * (int64_t)OS_TMR_CFG_TICKS_PER_SEC) + 999LL) / 1000LL;
  INT32U ticks = (INT32U) ticks64;

  // Saturate the value to the max value for a INT32U.
  if(ticks != ticks64)
  {
    ticks = DEF_INT_32U_MAX_VAL;
  }
  return ticks;
}
```

*LLMJVM over uCOS-III*

```
static OS_TICK LLMJVM_UCOSIII_timeToTick(int64_t time)
{
  if(time < 0)
  {
    return 0;
  }
  int64_t ticks64 = ((time * (int64_t)OSCfg_TmrTaskRate_Hz) + 999LL) / 1000LL;
  OS_TICK ticks = (OS_TICK) ticks64;

  // Saturate the value to the max value for an OS_TICK.
  if(ticks != ticks64)
  {
    return DEF_INT_32U_MAX_VAL;
  }
  return ticks;
}
```

### 5.2 MicroUI Limitations

#### 5.2.1 Software layers mode can throw a hardfault

Issue #12027

##### Description

The software layers mode (mode used when the platform implementation does not support hardware acceleration to manage the layers) can throw an hardfault when the flushing of the software layers buffer is required. The  $y_{max}$  coordinate is 1 pixel too high.

**Workaround**

The LLDisplay implementation must be updated in order to check the  $y_{max}$  coordinate. This value must not be higher than the LCD height minus one.

**5.2.2 Built-in platform throws an hard fault when MicroEJ application fills a polygon**

Issue #12186

**Description**

A wrong linker file is copied during the built-in platforms builds instead of using the file available in the display module. This is an old file which does not manage the `GraphicsContext.fillPolygon()` algorithm memory allocation. So when a MicroEJ application tries to fill a polygon on a built-in platform, an hard fault can occur (segmentation fault).

This error never occurs on platform built in the MicroEJ workspace.

**Workaround**

none.

**5.2.3 Alternate PNG image decodings and mutable image creations can throw an hard fault**

Issue #12334

**Description**

When an image is created using the runtime PNG decoder, a transparency array is created to store the pixels transparency. When this image is garbage collected, it can be re-used to create a mutable image (`Image.createImage(width, height)`). This kind of images cannot hold a transparency array. When this second image is garbage collected too, the transparency array of first image is garbage collected a second time, which can throw an hard fault exception.

**Workaround**

none.

**5.3 Tools Limitations****5.3.1 Heap Dumper does not strip XML comments related to string literals**

Issue #15348

**Description**

Heap Dumper is not able to load heap files which contains some Unicode characters whereas these characters are allowed in XML comments.

**Workaround**

Remove all Unicode characters in XML comments.

**5.3.2 Plugin installation issue with platform import.**

Issue #11022

**Description**

After installing a XFPF UI with a newer version of the frontpanel than the SDK, the workbench seems "to see" the plugin (cf configuration details) but it doesn't install it.

**Workaround**

Install the plugin manually.

## 6 MicroEJ SDK 3.0.0

### 6.1 Core Engine Limitations

#### 6.1.1 Error when returning from a method invoked from a nested call under certain circumstances

Issue #11441

##### Description

Under certain circumstances, returning from a method invoked from a nested call may lead to a system hardfault. Here is an example of a nested call that may produce the issue:

```
foo(a, bar(b));
```

The issue may occur when returning from the bar() method.

##### Workaround

Split the nested call into several instructions. Here is the work around for the previous example:

```
tmp = bar(b);  
foo(a, tmp);
```

### 6.2 MicroUI Limitations

#### 6.2.1 Software layers mode can throw an hardfault

Issue #12027

##### Description

The software layers mode (mode used when the platform implementation does not support hardware acceleration to manage the layers) can throw an hardfault when the flushing of the software layers buffer is required. The  $y_{max}$  coordinate is 1 pixel too high.

##### Workaround

The LLDisplay implementation must be updated in order to check the  $y_{max}$  coordinate. This value must not be higher than the LCD height minus one.

### 6.3 Tools Limitations

#### 6.3.1 Plugin installation issue with platform import.

Issue #11022

##### Description

After installing a XPFP UI with a newer version of the frontpanel than the SDK, the workbench seems "to see" the plugin (cf configuration details) but it doesn't install it.

##### Workaround

Install the plugin manually.



## 7 Document History

Date	Revision	Description
September 8th 2014	1.0	Initial release for MicroEJ SDK 3.0.0.
December 30th 2014	1.1	Added "Software layers mode can throw an hardfault" for MicroEJ SDK 3.0.0.
January 20th 2015	1.2	Added "Software layers mode can throw an hardfault" for MicroEJ SDK 3.1.0.
February 10th 2015	1.3	Added "Built-in platform throws an hard fault when MicroEJ application fills a polygon" for MicroEJ SDK 3.1.0.
February 13th 2015	1.4	Added "Core engine scheduling stopped on uCOS-II or uCOS-III" for MicroEJ SDK 3.1.0.
March 9th 2015	1.5	Added "Alternate PNG image decodings and mutable image creations can throw an hard fault" for MicroEJ SDK 3.1.0.
April 8th 2015	1.6	Added "Core engine scheduling stopped on uCOS-II or uCOS-III" for MicroEJ SDK 3.1.1.
November 20th 2015	1.7	Added "Core engine scheduling stopped on uCOS-II or uCOS-III" for MicroEJ SDK 3.1.2.
February 5th 2016	1.8	Added "Heap Dumper does not strip XML comments related to string literals" for MicroEJ SDK 3.1.0, MicroEJ SDK 3.1.1 and MicroEJ SDK 3.1.2.
October 24th 2016	2.0	Added "MicroEJ SDK 4.0.0" errata section.
February 1th 2017	2.1	Added "Plugin installation issue with platform import." for MicroEJ SDK 3.0.0, MicroEJ SDK 3.1.0, MicroEJ SDK 3.1.1 and MicroEJ SDK 3.1.2, MicroEJ SDK 4.0.0.